



# SIGN & DISPLAY ASSEMBLY GUNS & MIXING TIPS



**230 ml 10:1,  
Low-Resistance Manual  
Applicator Gun #11778**  
Use with Weld-On  
42, 230 ml Cartridges  
Use Mixing Tip #13147



**400 ml 4:1  
Low-Resistance Manual  
Applicator Gun #12613**  
Use with Weld-On 45, 400 ml Cartridges  
Use Mixing Tip #14043



**400 ml 4:1  
Manual Applicator Gun #13302**  
Use with Weld-On 45, 400 ml Cartridges  
Use Mixing Tip #14043

**470 ml / 490 ml 10:1  
Low-Resistance Manual  
Applicator Gun #11652**  
Use with Weld-On 11, 470 ml Cartridges  
Use Mixing Tip #13147



**470 ml / 490 ml 10:1  
"NEW" Manual Applicator Gun #150434**  
Use with Weld-On 30,31 and 32, 490 ml Cartridges  
Use Mixing Tip #150350




# SIGN & DISPLAY ASSEMBLY GUNS & MIXING TIPS



One Gun with Two Plungers

Includes 1 Each  
4:1 & 1:1 Plungers



4:1

1:1



**50 ml 1:1 / 4:1  
Manual  
Applicator Gun #13585**  
Use with Weld-On 45,  
43 ml Cartridge  
Use Mixing Tip #11195  
Use Plunger 4:1



**50 ml 1:1 / 4:1  
Manual  
Applicator Gun #13585**  
Use with Weld-On 55 & Weld-On 58,  
50 ml Cartridges  
Use Mixing Tip #11195  
Use Plunger 1:1



**50 ml 10:1  
Manual  
Applicator Gun 13584**  
Use with Weld-On 42,  
50 ml Cartridges  
Use Mixing Tip #13586  
Includes a 10:1 Plunger



Mixing Tip  
#150350

Mixing Tip  
#14043

Mixing Tip  
#13586

Mixing Tip  
#11195

Mixing Tip  
#13147